

FIRE SAFETY CERTIFICATE

No. M.C.B. / Fire / 2025-26 / 831

Dated: 16/02/2026

Certified that the Swami Vivekanand Govt. Model School (name of the building or premises) at Block - Kishungang, NH-27, Tejaji Ka Danda, Kishungang Dist. Baelun (address) comprised of NO basement(s) and Single floor (Ground + One floor) (upper floors) owned/ occupied by Swami Vivekanand Govt. Model School (name of the institution) have complied with the fire prevention and fire safety requirements in accordance with rule of State/ UT Fire Service Rules, and verified by the officers concerned of Fire Service on 16.02.2026 (date of inspection) in the presence of Mt. Mahavere Prasad Meenai (name and addresses of the Manager/ Secretary or his representative) and that the building/ premises is fit for occupancy upto classes Educational (X/ XII) With effect from 16.02.2026 for a period of 01 (one) year in accordance with rule and subject to compliance of specific conditions as appended:-

Mt. Mahavere Prasad Meenai (Receipt Signatory)

- 1.
- 2.
- 3.
- 4.

Issued on 16/02/2026 (date of issue) at Fire Department Baelun (place) by

*Strike out whichever is not applicable.

Signature with Seal:

Name :

Designation :



Name & Address of Department/ Office:

To Swami Vivekanand Govt. Model School
Block - Kishungang, Dist - Baelun (Paj) 325216

(Name & Address of the Institution)

ENDORSEMENT

The No Objection Certificate issued by Fire Service stand cancelled and annulled due to Empty condition of fire extinguisher. No maintenance not done (reasons to be recorded).

(Name and designation of the authorized signatory)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.





UDYAM - REGISTRATION NO
UDYAM - RJ-20-0001115

GSTIN - 08AZKPM5870D1Z4

H.O. MADAN VIHAR COLONY

JHALRA PATAN@326023

B.O. R.K. COLONY, BHILWARA@

PHONE : 9521640108, 7742122858, 7014907256

E-mail : jitendramodi111277@gmail.com

SHREE SHYAM AGENCY

The Fire Fighters



CERTIFICATE

For FIRE FIGHTING EQUIPMENTS - REFILING / SERVICING / NEW

This is to certified that our, Company have been Refilled / Servicing / New Fire Extinguisher Issue to

Date. 16-02-2026

S. No.

M/s.

Addr.

1768

नेताजी सुभाष चन्द कोस का लिका इगवास.

Company

किशनगंज. जिला- बारा.

S.No.	Type of Extinguisher		Capacity	Qty.	Type of job Done
1.	New / Refiling ABC Dry Powder Type	I II III IV	4kg	05	OK
2.	New / Refiling DCP Powder Type	I II			
3.	New / Refiling Co2 (Carbondioxide)	I II			
4.	New / Refiling Machanical Foam type	I II			
5.	New / Refiling Water type	I II			
			TOTAL	05 NOS	



Stand Bucket OK

Rifiling Date 16-02-2026

Next Due Date 15-02-2027

Instruction :- Fire Ext.

1. Extinguishers Should Be Operated By Trained Person.
2. Extinguishers Should Not Exposed Direct to Sun Light or any Heat
3. Extinguishers Should Properly Maintained



Sign. of Customer

For : SHREE SHYAM AGENCY

SHREE SHYAM AGENCY

The Fire Fighters

SSA

CERTIFICATE



For FIRE FIGHTING EQUIPMENTS - REFILING / SERVICING / NEW

This is to certified that our, Company have been Refilled / Servicing / New Fire Extinguisher Issue to

GSTIN - 08AZKPM5870D1Z4
H.O. MADAN VIHAR COLONY
JHALRA PATAN@326023
B.O. R.K. COLONY, BHILWARA@
PHONE : 9521640108, 7742122858, 7014907256
E-mail : jitendramodi111277@gmail.com

S. No. _____ Date. 16/02/2026
M/s. 1767
श्याम विवेकानन्द. राजकीय माडल स्कूल
Add. मिशन गेज. पिला. वारा (रा०) Company model school.

S.No.	Type of Extinguisher		Capacity	Qty.	Type of job Done
1.	New / Refiling ABC Dry Powder Type	I II III IV	4.5kg.	08	OK.
2.	New / Refiling DCP Powder Type	I II			
3.	New / Refiling Co2 (Carbondioxide)	I II	4.5kg.	06.	OK.
4.	New / Refiling Machanical Foam type	I II			
5.	New / Refiling Water type	I II			
			TOTAL	14 Nos	



Stand Bucket OK.
Rifiling Date 16/02/2026
Next Due Date 15/02/2027.

Instruction :- Fire Ext.
1. Extinguishers Should Be Operated By Trained Person
2. Extinguishers Should Not Exposed Direct to Sun Light or any Heat
3. Extinguishers Should Properly Maintained

