

**Executive Engineer, Construction Division No.3,
P. W. D. (B&R) Br., Batala Road, Amritsar**

To

The Principal,
Exceptional International School,
Vill. Sudhar, Teh Ajnala, Amritsar

No. 1664


Dated: 14/7/26

**Subject: Building Safety Certificate for the year 2026 to 2027.
(Exceptional International School, Vill. Sudhar, Tehsil Ajnala, Amritsar)**

Reference: Your office letter No. R2/P435 Dated 15.05.2026

Sub Divisional Engineer, Construction Sub Division Ajnala, PWD (B&R) Br., Amritsar vide his office letter No.60 dated: 22.06.2026 has reported this office that the building of "Exceptional International School, Vill. Sudhar, Tehsil Ajnala, Amritsar" has been visually inspected and found fit for human inhabitation for one year 2026-27 i.e. upto 31.03.2027.

DA/Performa I & II.


Executive Engineer,
Construction Division No.3,
P.W.D. (B&R) Br., Amritsar.

Endst.No. _____

Dated: _____

A copy of above is forwarded to Sub Divisional Engineer, Construction Sub Division Ajnala, P.W.D. (B&R) Br., Amritsar w.r.t. his letter No.60 dated 22.06.2026 for information and necessary action.

D.A./Nil

— SD —
Executive Engineer,
Construction Division No.3,
P.W.D. (B&R) Br., Amritsar.

A

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

(PART-I)


(To be filled in by the head of school, institute)

1. Name of the School Exceptional International School of Edu
2. Location Vill - Sudhar, Teh - Ajnala, Distt - Amrit
3. Plot Area 8266 Sqm
4. Covered Area of Building 2576292
5. Number of Stories 02
6. Year of Construction _____
- a) Frame Structure _____
- b) Brick masonry structure _____
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given:-
 - a) Name of Engineer with qualification G.S.S. Associates off app
 - b) Address of the Engineer Mahal Photostat Cawit Complex
Ajnala and N.C.M (A.S.R)
 - c) If structural drawing used in the construction, if available? _____
 - d) Name and address of Architect with qualification _____
8. Whether the building has been constructed for the purpose of
 - a) School Yes/No
 - b) Residential purpose and used for a school Yes/No
9. Materials used for Roofs
 - a) R.C.C. Slabs R.C.C. slabs
 - b) R.S. Joists & Battons _____
 - c) Wooden Joists and bottom _____
10. Material used for Walls
 - a) Mud Mortar Yes/No
 - b) Cement Mortar Yes/No
 - c) Lime Mortar Yes/No
11. Flooring
 - a) Conglomerate Yes/No
 - b) Terrace Yes/No
 - c) Brick Paving Yes/No
12. A detailed drawing indicating the doors along with windows and location fitting and windows is attached. _____
13. FOR FIRE SAFETY
 - a) Whether the width of the staircase is 1.5 mtr. Yes/No
 - b) Whether portable fire extinguisher exists Yes/No
 - c) Whether School building is free from inflammable & toxic material Yes/No
 - d) Whether cooking of food is done at a safe place Yes/No
 - e) Whether any Thatch or combustible material has been used Yes/No

14. Requirement for Fire Protection Arrangements under
NB-Part-IV
(For Building height less than 15 metre)

- | | |
|--|--------|
| a) Whether Hose Real provided | Yes/No |
| b) Whether down comer provided | Yes/No |
| c) Whether Automatic sprinkler provided | Yes/No |
| d) Whether underground static water storage tank of capacity
50000 Ltr.(if converted area exceeds 1500 sqm) | Yes/No |
| e) Whether over head tank of capacity 10000 Ltr.exists (in case
of hose real) 20000 Ltr. | Yes/No |
| f) Whether one eclectic and one diesel pump of 3 kg/cum
Pressure of capacity 1620 LPM, one electric pump of
Capacity 180 LPK exist near underground static tank. | Yes/No |
| g) Whether a pump 3 kg/cum pressure & 450/500 LPM
Exist near over head tank. | Yes/No |

Signature of the Head of School/
Institute



PART-II

(To be filled by the SDE of PWD (B&R) Department)

- a) I have visited the above mentioned school on dated 09/06/2026 and have visually inspected it from all angles of safety and find it fit for normal use as school building.
- b) In case any addition/alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used) 31/03/2027

30000 Ltr. per hour 01/06/2026 to 31/03/2027
10000 Ltr. per hour 01/06/2026 to 31/03/2027

J. E.
S. E.
Principal
Exceptional International School of Education
Village:-Sudhar, Amritsar
Affiliated to C.B.S.E. Code:-1631470
School Code:-23683

Devi
Sub-Division Engineer
Construction Sub-Division,
PWD (B&R), Ajnala.