

## BUILDING SAFETY CERTIFICATE

No. 3310

Dated:26/02/2024

It is certified that the existing building Saraswati Shishu Mandir H.S. School Biaora (name of the building or premises) at Behind Punit Cinema Suthaliya Road Biaora (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1	-	-	-	-	-

The building is owned/occupied by Saraswati Shishu Mandir H.S. School Biaora (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Nagar Palika (Name of Department/ Govt.) on 26/02/24 (date of inspection) in the presence of Mr. Ashok Dangi (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26/02/2024 for a period of **Five** years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 26/02/24 at Biaora M.C. by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal Ok मुख्य नगर पालिका अधिकारी

Name : Rais Khan

Designation : EMO

Name & Address of Department/ Office: Nagarpalika  
BIAORA